Dealer: US AUTO TRUST NEWPORT BEACH LLC

Model: Vantage Coupe Engine Number: 17795060072134

SCFSMGAW1KGN00950 Model Year:

Exterior Colour: Hyper Red

Interior Colour: All Obsidian Black Leather

Owner Benefits: Port of Entry: Brunswick, GA Suggested Retail Price at P.O.E. 3 years unlimited mileage warranty

\$149,995.00

OPTIONAL EQUIPMENT

24 hour roadside assistance

STANDARD FEATURES

Comfort and Convenience 8" Navigation System

garage door opener


Bluetooth Phone & Streaming Audio Satellite Radio with Trial Subscription - 1yr Radio, 3yr Traffic Data iPhone® Integration and USB Input 360 Degree Camera with Front & Rear Parking Sensors Power Folding Heated Exterior Mirrors 8-Way Power Front Seats with 3-Position Memory Power-Adjustable Tilt/Telescoping Steering 12" Color TFT LCD Cluster **Dual-Zone Automatic Climate Control** Rain-Sensing Wipers Electronic Park Brake (EPB) Auto-dimming interior rear-view mirror with

Gas Guzzler

TOTAL SUGGESTED RETAIL*

Transportation and handling

\$0.00 \$3,086.00 \$191,619.00



PARTS CONTENT INFORMATION

FOR VEHICLES IN THIS CARLINE: **U.S./CANADIAN PARTS CONTENT:**

MAJOR SOURCES OF FOREIGN PARTS CONTENT:

UK 66%

Gasoline Vehicle

more in fuel costs

Smog Rating (tailpipe only

10

over 5 years

average new vehicle.

compared to the

10

Germany 22%

NOTE: PARTS CONTENT DOES NOT INCLUDE FINAL ASSEMBLY, DISTRIBUTION OR OTHER NON-PARTS COSTS.

FOR THIS VEHICLE: FINAL ASSEMBLY POINT: Gaydon, Warwickshire, UK

COUNTRY OF ORIGIN: ENGINE PARTS:

GERMANY

TRANSMISSION PARTS: **GERMANY**

BUMPER QUALITY LABEL

THIS VEHICLE IS EQUIPPED WITH A FRONT BUMPER THAT HAS BEEN TESTED AT AN IMPACT SPEED OF 2.5 MILES PER HOUR, AND A REAR BUMPER THAT HAS BEEN TESTED AT AN IMPACT SPEED OF 2.5 MILES PER HOUR AND HAS SUSTAINED NO DAMAGE TO THE VEHICLE'S BODY AND MINIMAL DAMAGE TO THE BUMPER AND ATTACHMENT HARDWARE. MINIMAL DAMAGE TO BUMPER MEANS DAMAGE THAT CAN BE REPAIRED WITH THE USE OF COMMON REPAIR MATERIALS WITHOUT REPLACING PARTS. THE STRONGER THE BUMPER THE LESS LIKELY THE CAR WILL REQUIRE REPAIR AFTER A LOW SPEED COLLISION. (FOR CORNERS, THE IMPACT IS 60% OF THAT STATED ABOVE).

IMPORTANT NOTICE

THESE IMPACT SPEEDS ARE GOOD FAITH ESTIMATES OF THE SPEEDS AT WHICH THE DESCRIBED EXTENT OF BUMPER DAMAGE WILL NOT BE EXCEEDED BASED ON REASONABLE ENGINEERING JUDGMENT AND DATA FROM TESTING PURSUANT TO THE FEDERAL BUMPER STANDARD WHICH PROHIBITS DAMAGE TO THE VEHICLE BODY OR SAFETY SYSTEM IN 2.5 MPH IMPACTS, BUT SETS NO LIMIT ON DAMAGE TO BUMPERS AND THEIR ASSOCIATED COMPONENTS AND FASTENERS. THIS VEHICLE MEETS THE FEDERAL BUMPER STANDARD AT 2.5 MPH FRONT AND REAR, AND 1.5 MPH ON THE BUMPER CORNERS.

GOVERNMENT 5-STAR SAFETY RATINGS

This vehicle has not been rated by the government for overall vehicle score, frontal crash, side crash or rollover risk.

Source: National Highway Traffic Safety Administration (NHTSA) www.safercar.gov or 1-888-327-4236

^{*}Total amount does not include state and local taxes or dealer installed accessories